

BMW X1 xDrive18dA 150 Lounge

Reference	7941
CC	1995
HP	150
CO ²	124
Body type	SUV/4x4
Status	Status used
1st registration	9/03/2018
Mileage	13800
Fuel	Diesel
Colour	Grey
	Tissue Black



Options title

4WD	Accoudoir central	Active pedestrian protection
Alloy wheels 18	Automatic climate control	Automatic trunk lid mechanism
Bluetooth	Central locking	Cruise Control
Electric side mirrors	Electric windows	Electrochromic rearview mirror
ESP	Front parking sensor	Heated Seats
Immobiliser	Isofix	Light sensor
MP3	Multifunction steering wheel	Navigation system (GPS)
Park Assist	Parking camera	Particulate filter
Passenger airbag disconnectable	Power steering	Projecteurs LED
Rain sensor	Rear parking sensor	Tire pressure display
Trip computer	USB input	With service history