

## MINI Cooper S Countryman 2.0 192 Chili Auto.

|                     |                   |
|---------------------|-------------------|
| Referin             | 7677              |
| CC                  | 1998              |
| CP                  | 192               |
| CO <sup>2</sup>     | 137               |
| Categorie           | SUV/4x4           |
| Stare               | Second hand       |
| Prima înmatriculare | 17/05/2018        |
| Km                  | 4900              |
| Carburant           | Essence           |
| Culoare             | Bleu              |
|                     | Cuir partiel Noir |



### Opiuni

|                                |                                     |                                       |
|--------------------------------|-------------------------------------|---------------------------------------|
| Acces confort                  | Accoudoir central                   | Airbag pasager detasabila             |
| Bluetooth                      | Clim automat                        | Computerul de bord                    |
| Cruise Control                 | Cu carte de service                 | Eclairage ambiant                     |
| ESP                            | Farurile de cea                     | Geamuri electrice                     |
| Imobilizator                   | Inchidere centralizata              | Intrare USB                           |
| Isofix                         | Jante din aliaj 18                  | MINI Service Inclusive 5ans/60.000kms |
| MP3                            | Oglinda retrovizoare electrochromic | Oglinzi electrice                     |
| Park Assist                    | Projecteurs LED                     | Protection active des piétons         |
| Rabatare retrovizoare electric | Real Time Traffic Information       | Scaune incalzite                      |
| Scaune sport                   | Senzor de lumin                     | Senzor de parcare din fa?a            |
| Senzor de parcare spate        | Senzor de ploaie                    | Servodirectie                         |
| Shift Paddles                  | Sistem de navigatie                 | Système d'appel d'urgence             |
| Tire pressure display          | Vitres arrières surteintées         | Volan multifunctional                 |